

| Orbit | Date | Entry - UTC | Level | Entry Type | ID Content/Transition | Mode | Source | Remark |
|-------|-------------|-----------------------|------------|------------------------------|-----------------------|-------------|-----------------------|--|
| 5491 | 19-MAR-2003 | 2003.078.16.31.10.090 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.16.31.10.097 | Instrument | COMPLEMENTARY FAILURES | --- | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.16.31.10.097 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.17.40.51.035 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.17.40.51.043 | Instrument | COMPLEMENTARY FAILURES | --- | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.17.40.51.043 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.17.41.37.199 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.17.41.37.207 | Instrument | COMPLEMENTARY FAILURES | --- | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5491 | 19-MAR-2003 | 2003.078.17.41.37.210 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5492 | 19-MAR-2003 | 2003.078.18.05.16.214 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5492 | 19-MAR-2003 | 2003.078.18.05.16.222 | Instrument | COMPLEMENTARY FAILURES | --- | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5492 | 19-MAR-2003 | 2003.078.18.05.16.226 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5492 | 19-MAR-2003 | 2003.078.18.11.45.636 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5492 | 19-MAR-2003 | 2003.078.18.11.45.644 | Instrument | COMPLEMENTARY FAILURES | --- | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5492 | 19-MAR-2003 | 2003.078.18.11.45.644 | Instrument | MACROCOMMAND EXECUTION ENTRY | START TIMELINE | Measurement | Report Format | erroneous start of timeline due to duplication of MPS schedule in recovery |
| 5502 | 20-MAR-2003 | 2003.079.10.57.34.000 | Instrument | AUTONOMOUS SWITCHING | goto R/W-WAIT | R/W-WAIT | Unavailability Report | MCMD CCA check error triggered due to missing s/w patch |